


Ref 10.00 dB  
Div 10.0

Step 20.000000 MHz  
Atten --

VBW --

# Radiun\_MZ-Qhybrid S/N 101 sum-0°



Signal Hound SA44B, Serial: 30300214, Firmware: Version 2.10


220 pts in 491 ms  
2021/10/17 18:10:30

Ref 10.00 dB  
Div 10.0

Step 20.000000 MHz  
Atten --

VBW --

# sum-90°



Signal Hound SA44B, Serial: 30300214, Firmware: Version 2.10

220 pts in 816 ms  
2021/10/17 18:11:00


Ref 10.00 dB  
Div 10.0

Step 20.000000 MHz  
Atten --

VBW --

# Radiun\_MZ-Qhybrid S/N 102

## sum-0°



Signal Hound SA44B, Serial: 30300214, Firmware: Version 2.10


220 pts in 1043 ms  
2021/10/17 17:52:28

Ref 10.00 dB  
Div 10.0

Step 20.000000 MHz  
Atten --

VBW --

## sum-90°



Signal Hound SA44B, Serial: 30300214, Firmware: Version 2.10

220 pts in 893 ms  
2021/10/17 17:53:23


Ref 10.00 dB  
Div 10.0

Step 20.000000 MHz  
Atten --

VBW --

# Radiun\_MZ-Qhybrid S/N 103

## sum-0°



Signal Hound SA44B, Serial: 30300214, Firmware: Version 2.10


2021/10/17 17:58:21

Ref 10.00 dB  
Div 10.0

Step 20.000000 MHz  
Atten --

VBW --

## sum-90°



Signal Hound SA44B, Serial: 30300214, Firmware: Version 2.10

2021/10/17 17:58:49